



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** OnStar WIFI Inoperative After VCIM Replacement Or Reprogramming Event

**Models:** 2015 All GM Passenger Car and Light Duty Trucks  
With OnStar Gen10 WIFI (RPO VV4)

### Condition/Concern

A customer may comment that OnStar WIFI is inoperative after a VCIM replacement or after a reprogramming event because "WIFI Activation" is not available in TIS2WEB at this time.

### Recommendation/Instructions

If this concern is experienced, verify the vehicle has the WIFI option by confirming that the vehicle has RPO VV4.

If so, please record the following information from GDS2 / Telematic Control Module / Identification Information and call GM Technical Assistance for further direction.

GM End Model part number

Mobile Equipment Identifier

OnStar Customer Identifier

Mobile Identification Number

Mobile Directory Number

### Warranty Information

For vehicles repaired under warranty, please refer to the latest version of bulletin 06-08-47-001 for warranty information on control module reset/configuration.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION